



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	106	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3407		Menlo	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_A\A_2004_0902Image0007.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 106

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\106.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	106	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3504		Menlo	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_A\A_2004_0902Image0008.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 106

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\106.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	106	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3400		Menlo	DR

Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:
---------------------	------------------	------------------	--------------	------------------

Sector:	2=Private	Drainage Area:	25
----------------	-----------	-----------------------	----

Comments: hole in ground

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_A\A_2004_0902Image0009.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 106

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\106.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	106	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3400		Menlo	DR

Source Type:	02= Service Line	Location:	5=Sidewalk	Severity:
Sector:	1=Public	Drainage Area:	25	

Comments: water meter

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_A\A_2004_0902Image0010.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 106

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\106.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	106	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3317		Menlo	DR

Source Type:	18= Other	Location:	9=Yard-Side	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments: foundation

SMOKE TEST PHOTOS



Photo No: 3

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0003.JPG

Image Status: Image found and displayed.



Photo No: 5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0005.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 106

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\106.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	106	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3317		Menlo	DR

Source Type:	18= Other	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	100	

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0004.JPG

Image Status: Image found and displayed.



Photo No: 5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0005.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 106

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\106.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	106	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3315		Menlo	DR

Source Type:	18= Other	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0007.JPG

Image Status: Image found and displayed.



Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0008.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 106

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\106.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	106	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3309		Menlo	DR

Source Type:	02= Service Line	Location:	6=Curb	Severity:
Sector:	1=Public	Drainage Area:	20	

Comments: crack in sidewalk

SMOKE TEST PHOTOS




Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0009.JPG

Image Status: Image found and displayed.



Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0010.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 106

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\106.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	106	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	5	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3315		Menlo	DR

Source Type:	02= Service Line	Location:	5=Sidewalk	Severity:
Sector:	1=Public	Drainage Area:	30	

Comments: smoke from water meter

SMOKE TEST PHOTOS



Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0011.JPG

Image Status: Image found and displayed.



Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0008.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 106

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\106.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	107	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5914		Highgate	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_A\A_2004_0902Image0011.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 107

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\107.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	107	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5902		Highgate	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 12

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_A\A_2004_0902Image0012.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 107

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\107.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	107	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	Y
Defect No:	1	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:	
6009		Highgate	DR	
Source Type:	14= Catch Basin	Location:	6=Curb	Severity:
Sector:	1=Public	Drainage Area:	5200	
Comments:	corner of streets			

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 12

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0012.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 107

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\107.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	107	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6003		Highgate	DR

Source Type:	02= Service Line	Location:	4=Driveway	Severity:
Sector:	2=Private	Drainage Area:	75	

Comments: under a car

SMOKE TEST PHOTOS



Photo No: 13

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0013.JPG

Image Status: Image found and displayed.



Photo No: 14

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0014.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 107

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\107.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	107	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6001		Highgate	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	125	

Comments:

SMOKE TEST PHOTOS



Photo No: 15

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0015.JPG

Image Status: Image found and displayed.



Photo No: 17

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0017.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 107

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\107.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	107	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6001		Highgate	DR

Source Type:	18= Other	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	125	

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 16

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0016.JPG

Image Status: Image found and displayed.



Photo No: 17

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_B\B_2004_0902Image0017.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 107

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\107.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	108	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3403		Parkington	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 13

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_A\A_2004_0902Image0013.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 108

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\108.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	108	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	4	Priority CCTV:	

House Number	3405	Street Prefix:		Street Name:	Parkington	Street Type:	AVE
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:			
Sector:	2=Private	Drainage Area:	25				
Comments:							

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 14

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_A\A_2004_0902Image0014.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 108

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\108.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	108	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3409		Parkington	AVE
Source Type:	02= Service Line	Location:	5=Sidewalk
Sector:	2=Private	Drainage Area:	25
Comments:	crack		

SMOKE TEST PHOTOS




Photo No:
Filename Path:

Image Status: No image name specified.

Photo No: 15

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_A\A_2004_0902Image0015.JPG

Image Status: Image found and displayed.

Photo No:
Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 108

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\108.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	108	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	4	Priority CCTV:	

House Number	3409	Street Prefix:		Street Name:	Parkington	Street Type:	AVE
Source Type:	12= MH Frame Seal	Location:	2=Paved Asphalt	Severity:			
Sector:	1=Public	Drainage Area:	3500				
Comments:	Sanitary sewer						

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 17

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_A\A_2004_0902Image0017.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 108

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\108.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	108	Date:	9/2/2004	MeterBasin:	01_WR22
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	5	Setup No:	4	Priority CCTV:	

House Number	3404	Street Prefix:		Street Name:	Parkington	Street Type:	AVE
Source Type:	02= Service Line	Location:	6=Curb	Severity:			
Sector:	1=Public	Drainage Area:	75				
Comments:	hole in ground						

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 18

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0902-2004\T-1\PLAYER_A\A_2004_0902Image0018.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 108

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\108.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.